

Technical Service Bulletin

MODEL(S)
AFFECTED: **Tennant 5680**

SUBJECT: Actuators being damaged due to improper installation/adjustment.

PURPOSE: Properly install/adjust actuator.

NOTES: Kit number 9003318. The Instruction Bulletin for this kit is IB 340845.
Refer to IB 340845 for instructions how to properly install and adjust the actuator (Tennant part number 397721) on 5680 machines. The actuator can be easily damaged if it is not installed and adjusted **as instructed in the IB.**
Questions, contact the Tennant Customer Service Department at (800) 553-8033 or (763) 513-2850.

WARNING: Always disconnect battery cables from machine before working on electrical components.




FIG. 1