Release Date: February 6, 2013



Technical Service Bulletin

MODEL(S)
AFFECTED:
T7 and R14 - Models manufactured before serial number 10604586 (February 6, 2013).

T7 models manufactured in Europe before April, 2013.

SUBJECT: Potential forward/reverse directional switch malfunction. Due to possible carbon buildup on switch

contacts, the reverse position of the switch may not function or function properly.

PURPOSE: If you experience the above condition, install switch part number 1072040.

The new switch is designed to address carbon buildup. It is a direct replacement.

NOTES: Warranty Information: Standard warranty terms apply.

Forward/Reverse Directional Switch



Existing Switch (p/n 1013763)



To identify the difference between the existing switch and new switch, the new switch is marked with the new part number 1072040. The existing switch does not include a part number.



New Switch

(p/n 1072040)

