Date: July 19, 2016



## **Technical Service Bulletin**

MODEL(S) AFFECTED: T12 Rider Scrubber

Models manufactured before:

June 16, 2016 (Americas), July 14, 2016 (EMEA), July 18, 2016 (APAC)


SUBJECT: Defective squeegee guide blocks. These parts may contain a void which will weaken the structure,


making it prone to breaking when side squeegee door is opened.


PURPOSE: If you have existing stock of part numbers 1201455 and 1200689, please scrap and order new

replacement parts. All Tennant inventory has been replaced with quality parts.

**NOTES:** Warranty Information: Standard warranty terms apply.







Cut-away view of defective block