

## TECHNICAL SERVICE BULLETIN 98800-012

DATE: 01/01/98

## TITLE: PROPELLING MOTOR MOUNTING HARDWARE REPLACEMENT

APPLICABLE MACHINES: 800,810

## SYNOPSIS:

The hardware that mounts the motor to the Drive Support may loosen and need to be retorqued or replaced.

- 1. Jack the rear of the machine up to take the weight off the rear wheel. Place jack stands under each corner and then check the 4 mounting screws that mount the motor to the drive support.
- 2. If the hardware that mounts the propel motor is M12–1.75 x 70 hex head screw, they should be replaced with the following hardware:
  - (4) socket head cap screws 1/2"-13 x 2.75 (p/n 39305)
  - (4) 1/2" SAE flat washers (p/n 32486)
  - (4) hexlocnyln nuts 1/2"-13 (p/n 32985)
- 3. Once installed, torque to 90–110 ft.lbs. If existing hardware is already the cap screws, re-check the torque and correct if necessary.

