



BATTERY CONNECTOR MOUNT KIT

INSTALLATION INSTRUCTIONS:

TOOL REQUIRED: Phillips Screwdriver.

(Installation Time: 30 min.)

1. Fasten the battery connector bracket to the vacuum motor mount plate using hardware as shown.
2. Attach the battery connector to the battery connector bracket using hardware as shown. Route battery connector cables below the bracket.

#606689 KIT CONTENTS

| P/N | Description | Qty |
|--------|-------------------------|-----|
| 606688 | Bracket, Bat. Connector | 1 |
| 140831 | Screw, 6-32x5/8 | 2 |
| 140019 | Washer, #6 ext. | 2 |
| 140887 | Screw, 10-24x3/8 | 2 |
| 140519 | Nut, 10-24 Kep | 2 |

