

Technical Service Bulletin

MODEL(S) AFFECTED: **Tennant T16 Scrubbers**
(North America Serial Numbers 00000-22033 / TNV Serial Numbers 0000-0109)

SUBJECT: Roll pin in the steering chain sprocket potentially coming loose.

PURPOSE: Secure roll pin in steering chain sprocket with roll pin retaining kit.

NOTES: Order Roll Pin Retaining Kit - 322311. The IB (Instruction Bulletin) for this kit is IB 328291. Refer to IB 328291 for installation instructions.
Questions, contact Tennant Customer Service Department at (800) 553-8033 or (763) 513-2850.
Warranty Information: Standard Terms Apply.

