

Technical Service Bulletin

MODEL(S) AFFECTED: T1B Scrubber equipped w/ lithium-ion battery



SUBJECT: Lithium-ion Battery Charger HB250-12 (Part No. 1065754) - Manufacturer Defect (polarity wiring issue)
Affected chargers are identified with manufacturer date code 080619xxxx (mm/dd/yy/xxxx).
Defective charger behavior: All three LEDs flash green repeatedly when the DC cord is connected to the machine. Battery will not take a charge.

PURPOSE: Identify and return all defective chargers from field for replacement.

NOTES: **Warranty Information:** Standard warranty terms apply.

Lithium-ion Battery Charger HB250-12 (Part No. 1065754)

Affected Chargers
Manufacturer Date Code
(Aug 06, 2019)



All three LEDs flash green repeatedly

