



TECHNICAL SERVICE BULLETIN

DATE: 920109


**TITLE:
IGNITION SWITCH CONNECTIONS**

**APPLICABLE MACHINES:
95, 250, 255, 275, 360**

SYNOPSIS:

The terminal connections are difficult to identify on ignition switch Tennant Company part number 55258.

The ignition switch terminal connection identification marks can be covered with sealant, making it difficult to read the marks. Here are the identification marks for reference.



IGNITION SWITCH TERMINAL IDENTIFICATION MARKS