



TECHNICAL SERVICE BULLETIN

No. 985700-007
Machine: 5700, all
System: Vacuum

NEW STYLE VACUUM FAN FILTER KIT

PRODUCT IMPROVEMENT:

THE EARLY TYPE VACUUM FAN SCREEN LOCATED UP UNDER THE SOLUTION TANK BY THE VACUUM FAN ASSEMBLY COULD BECOME CLOGGED WITH LINT, PAPER FIBERS, AND ETC. IT COULD ALSO ALLOW FOAM TO ENTER THE VACUUM FAN IF THE RECOVERY TANK IS OVERFILLED WITH FOAM.

REMEDY / COURSE OF ACTION:

Please follow the procedure instructions.

1. ORDER VACUUM FAN FILTER KIT PART NUMBER 370114.

SPECIAL TOOLS / CONSIDERATIONS: NONE

(Estimated Time to complete: 5 MINUTES)

PROCEDURE:

(Refer to Figure 1)

1. Install new vacuum fan filter as per instructions in the kit and picture below. The old filter can be disposed of, or cleaned and retained on the machine. (Note) This part is being obsoleted. The new filter is made of a synthetic fiber material and can be cleaned by running it under tap water. (CAUTION) High pressure air and water could damage the fibers.

FOR SAFETY: Before leaving or servicing machine, stop on level surface and set parking brake. Then turn off machine and remove key.



WARNING: Always disconnect battery cables from machine before working on electrical components.

