



## **TECHNICAL SERVICE BULLETIN 98800–014**

**DATE: Revised 11/97**

**TITLE:**

**MAIN BRUSH MOTOR CASE DRAINS**

**APPLICABLE MACHINES:**

**800,810**

---

**SYNOPSIS:**

Main brush motor should have case drain lines if motor shaft seal leak problems occur.

---

On model 800 machines prior to serial number 1177 and model 810 machines below serial number 2065, a case drain line should be added to help prevent future motor seal leaks. A case drain line kit is available under part number 77756.