



## TECHNICAL SERVICE BULLETIN

No. 996100-001  
Machine: 6100 IC  
System: Filter

(TITLE)

### **(INCORRECT PART NUMBER )**

#### **PRODUCT CHANGE DESCRIPTION:**

In manual 330230 the Filter Shaker Solenoid was incorrectly listed as 379761. The correct number is 379760. This should be corrected in the next manual revision. Please make a note of this in your manuals. The 379761 is the 36 volt version of the solenoid and will not operate properly in the 12 volt machine.