



INSTRUCTION BULLETIN

No. 2815
Machines: 42E Scrub-
ber, 42 HD Scrubber
Published: 9-85

Installation Instructions for Pin Replacement Kit 33263.

This kit contains a bolt and nut to replace (1) pin 28567. Please follow the step-by-step directions.

1. Park the machine on a level surface. Turn off the engine/motor and set the parking brake, if present.

WARNING: Always turn off the engine/motor when working on the machine.

2. Replace the broken pin with the bolt and nut in the kit and the (2) existing washers.

BILL OF MATERIAL FOR KIT 33263

TENNANT®

Part No.	Description	Qty.
48418	SCREW, 1/4 - 20 x 4-1/2"	1
32981	NUT, Hex lock nylon, 1/4 - 20	1




Fig. 1 - REPLACEMENT OF 28567 PIN

TENNANT COMPANY
P.O. Box 1452
Minneapolis, MN 55440-1452
(612)540-1200