

# Technical Service Bulletin

**MODEL(S) AFFECTED:** **T500/T500e Walk-behind Scrubber**

N. America models manufactured before serial number 10865727 (Aug 24, 2017)

EMEA models manufactured before serial numbers T500-U10420 and T500E-U10384 (Sept 25, 2017)


APAC models manufactured before December 1, 2017

**SUBJECT:** Solution filter bowl ground clearance.


**PURPOSE:** For unique applications that may require additional ground clearance, rotate the filter bowl 90 degrees as shown below.

**NOTES:** **Warranty Information:** Standard warranty terms apply.

Solution filter bowl ground clearance on existing machines.



To increase ground clearance, simply rotate the filter bowl 90 degrees toward the front of the machine as shown. Re-secure with cable-ties.



For models manufactured after the above dates, the machine frame was modified to allow the filter bowl to be orientated horizontally toward the rear of machine as shown below. This provides convenient access for filter bowl removal. A yellow maintenance touch point label was also added.

